

Figure 7-41

Bearing. Draw necessary views, with full section (Layout A-3).\*




Figure 7-43
Column Support. Draw necessary views, with full section (Layout A–3).\*




Figure 7-44
Centering Bushing. Draw necessary views, with full section (Layout A–3).\*




Figure 7-45
Special Bearing. Draw necessary views, with full section (Layout A–3).\*




Figure 7-47
Cup Washer. Draw necessary views, with full section (Layout A–3 or A4–3 adjusted).\*




Figure 7-48

Fixed Bearing Cup. Draw necessary views, with full section (Layout A–3 or A4–3 adjusted).\*




Figure 7-49
Stock Guide. Draw necessary views, with half section (Layout B–4 or A3–4 adjusted).\*




Figure 7-50

Bearing. Draw necessary views, with half section. Scale: half size (Layout B–4 or A3–4 adjusted).\*




Figure 7-55

Rocker Arm. Draw necessary views, with revolved sections (Layout B–4).\*




Figure 7-56

Dash Pot Lifter. Draw necessary views, using revolved section instead of removed section (Layout B–4).\*




Figure 7-57

Adjuster Base. Given: Front and top views.

Required: Front and top views and sections A-A, B-B, and C-C.

Show all visible lines (Layout B-4).\*




Figure 7-58

Mobile Housing. Given: Front and left-side views. Required: Front view, right-side view in full section, and removed section A–A (Layout B–4).\*




Figure 7-61

Traverse Spider. Given: Front and left-side views. Required: Front and right-side views and top view in full section (Layout B–4 or A3–4 adjusted).\*




Figure 7-62

Gland. Given: Front, top, and partial left-side views. Required: Front view and right-side view in full section (Layout A–3 or A4–3 adjusted).\*




Figure 7-63

Bracket.Given:Front and right-side views.
Required:Take front as new top; then add right-side view, front view in full section A–A,and sections B–B and C–C (Layout B–4 or A3–4 adjusted).\*




Figure 7-66

Strainer Body. Given: Front and bottom views.

Required: Front and top views and right-side view in full section
(Layout C–4 or A2–4).\*




Figure 7-71
Transmission Part. Draw necessary views with full section.




Figure 7-74

Plastic Spacer. Draw all necessary views with one half section (Layout A-3).\*




Figure 7-75

Motor: Draw all required views with one half section (Layout B-4 or A3-4 adjusted)




Figure 7-76

Mounting Pin. Draw front and top view. Make one view a half section (Layout B-4 or A3-4 adjusted).\*